

# SLOPE FAILURE IN EXPANSIVE MARLS

Rupture de talus dans des marnes expansives

Böschungsbruch in quellfähigen Mergeln

GONZALEZ DE VALLEJO\*, L., CAMPOS DE ORELLANA\*, J. A.

BERZAL\*, J. L. and LINARES-RIVAS\*, A.

\* Empresa Nacional Adaro de Investigaciones Mineras, S.A.

Serrano, 116 - Madrid, Spain

## ABSTRACT

A case of slope failure in marls of expansive nature with clayey gouge materials along discontinuities is presented. Due to the failure of a plane and a wedge during construction, the stability conditions anticipated during design were compared with those prevailing during excavation. It was proved that the main factors affecting the instability were the seepage forces of rainfall water flowing into the excavation area and the conventional and overloaded blasts. The need of technical assistance during construction is emphasized as an important part of the design.

## RESUME

On étudie un cas de glissement d'un talus en marnes expansives avec des discontinuités argileuses. On a pu montrer que les causes principales agissant sur l'instabilité étaient les filtrations de l'eau provenant de la pluie et l'action des explosifs. On en déduit l'intérêt de l'assistance technique pendant l'exécution des travaux.


## ZUSAMMENFASSUNG

Es wird ein Fall von Böschungsbruch in schwellfähigen Mergeln mit tonigen Kluffbestegen vorgestellt. Aufgrund eines ebenen und Keilbruches während der Bauarbeiten wurden die Standsicherheitsbedingungen, die während der Projektierung erwartet wurden, mit den bei der Ausführung herrschenden verglichen. Es wurde nachgewiesen, dass die für die Unsicherheit hauptverantwortlichen Faktoren die Strömungskräfte des Regenwassers im Aushubsbereich sowie die konventionellen, zu stark geladenen Sprengungen waren. Auf die Notwendigkeit einer technischen Assistenz während des Baus als einen wichtigen Bestandteil des Projektes wird hingewiesen.

## INTRODUCTION

The design of an excavation of 25 x 20 m length and 25 m depth was required to set up a crushing plant of marls for a cement manufacturing company in Olazagutia (Navarra, North East Spain). The site was located on a hill side area formed by stratified marls dipping from 30 to 40 degrees southward. Site investigations consisted on structural analysis of discontinuities, borehole drilling, RQD determination, weathering grades, point load tests (PLT), and permeability assesstment and sampling. Because of the proximity to a quarry composed by similar materials it was possible to carry out a back analysis of the stability of fallen rocks. Laboratory tests mainly consisted on shear box tests along discontinuities from borehole core samples and undisturbed block samples. Compressive strength, slate durability tests (SDT) and other index tests were also performed, besides X-Ray mineralogy determination. The rock material consisted of softs calcareous marls, grey coloured of very fine grained, with 70% of  $\text{CO}_3\text{Ca}$ , 14% of montmorillonite, 8% of illite, 5% of quartz and 2% of chlorite. The major dis-

continuities were the stratification planes, shear joints and tension joints. Discontinuity roughness varies from smooth to undulating and some of them, particularly the stratification planes, showed clayey gouge material of 1 - 2 cm thick. SDT results carried out according to the suggested methods of ISRM indicated a high durability index. However, it was observed that longer periods of time and increasing number of cycles than those recommended by ISRM lead to very low durability index. This low index indicate much better the swelling mineral composition of the marls. Shear strength parameters are illustrated in figure 1 together with shear strength back analysis and shear box tests results. Acceptable agreement between both results were found. It is remarkable the low values of the shear strength along discontinuities filled with clay material, even lower than those obtained with the same clay but in remoulded state. For further discussion of the geotechnical properties of this material it is referred to Gonzalez de Vallejo and Berzal (1976).



- Back analysis results
- △ Ondulated discontinuity with calcite gouge
- ▲ Smooth discontinuity without gouge material
- Closed and clean discontinuity
- Smooth discontinuity with clay infilling
- Remoulded clay infilling

Fig. 1.— Results of shear stresses (residuals) from laboratory shear box tests and back analysis of failed slopes.

#### DESIGN CRITERIA

It was requested to undertake the design of the excavation not only under economic considerations but under safety conditions, therefore a conservative criteria was adopted in the selection of the shear strength parameters for design purposes. An angle of internal friction of 30 degrees was taken for discontinuities free of clayey gouge materials and 25 degrees for those with clay fillings. In both cases a cohesion of 20  $\text{KN/m}^2$  was chosen. No water table were intercepted during the site investigations neither regional hidrogeological evidences. None of both detected the presence of a high water table in the area; therefore it was supposed a drained slope condition.

A short term condition was considered because, once the excavation were finished, the room between the slopes and the walls of the plant (Fig. 6) had to be filled with rock material, therefore a factor of safety 1.2 was taken for design. The stability analysis was carried out using John (1971) and Hoek and Bray (1974)-approaches to the problem.

Based on economic and construction reasons, two solutions were considered. The first one consisted to excavate the North, South and East slopes to an angle of 80 degrees and the West slope to 70 degrees. In this case, the North

slope should require reinforcement to set back the factor of safety of plane  $P_1$ , which was 0.80 (Fig. 2 and table 1), to the factor of safety established by the design. It was estimated that a force of 2,200 Mg would be appropriate and obtained by means of postensioned anchors. Additional reinforcing bolts could be necessary to stabilised potential wedges (w8 and w9) in those places where the safety factor were 0.90. Similary, the South slope would require bolting for the unstable wedge w7 (F. of. S. 0.80). West slope would also need an additional force of 1,900 Mg to restitute the safety factor of plane  $P_4$  (0.90) by means of anchoring.

The second solution consisted to excavate the South and East slopes to 80 degrees, North slope to 60 degrees and West slope to 55degrees, requiring in all cases some boltings. But in both solutions it was recommended to carry out the recommendations listed in Table 2 (left column). Independently, it was suggested to choose the first solution because it could be implemented in a shorter period of time and would avoid the need of an extraexcavation of 3,500  $\text{m}^3$  and the filling of this room after construction. The cost of both solution appear to be similar, although the second one was slightly cheaper. Solution two will not need special geotechnical works, e.g. anchoring.


TABLE 1.- COMPARAISON OF THE STABILITY CONDITIONS ANTICIPATED BY THE DESIGN AND THOSE PRESENT DURING EXCAVATION

SLOPES FACES	ANTICIPATED BY DESIGN		PRESENT DURING EXCAVATION		BEHAVIOUR DURING EXCAVATION	
	Unstable discon. according with Fig. 2	F. of S. unstable discon. of Fig. 2 for design condit. (1)	Unstable discon. according with Fig. 3	F. of S. unstable discon. of Fig. 3 for design condit. (1)	Half of excavation = 10 m deep	End of Excavation = 20 m deep
NORTH	Plane P <sub>1</sub> Wedges W <sub>8</sub> +W <sub>9</sub>	F. of S. > 1,2 See recommendations during construction specified by design. Table 2	Planes P <sub>1</sub> +P <sub>2</sub> Wedges W <sub>1</sub> +W <sub>2</sub> + W <sub>3</sub> +W <sub>4</sub>	F. of S > 1,2	No major stability problems. Partial failure of blocks less than 3 m <sup>3</sup> .	Plane P <sub>2</sub> failed (approx. Vo. 400 m <sup>3</sup> ) See text for discussion
SOUTH	Wedge W <sub>7</sub>		Plane P <sub>3</sub> Wedges W <sub>5</sub> +W <sub>6</sub>		Wedge W <sub>1</sub> failed (approx. vol. 15 m <sup>3</sup> ). See text for discussion	Minor stability problems. Partial failure of blocks less than 3 m <sup>3</sup>
WEST	Plane P <sub>4</sub>		Wedges W <sub>1</sub> +W <sub>2</sub> + W <sub>3</sub> +W <sub>4</sub>			
EAST	None	-	none	-	haulledge ramp	haulledge ramp

(1) For Short term stability Conditions, F. of S.  $\geq 1,2$   
 angles of slope faces 60°,  $\phi = 30^\circ$  or 25°  
 c = 20 KN/m<sup>2</sup>, and no water pressures.

TABLE 2.- COMPARAISON OF THE RECOMMENDATIONS GIVEN BY THE DESIGN AND THOSE FOLLOWED DURING EXCAVATION

DESIGN RECOMMENDATIONS	CONDITIONS DURING EXCAVATION
a) Necessary to excavate under geotechnical supervision	No geotechnical supervision
b) Diversion of surface waters out side area of excavation and to proceed it during the dry season	Surface waters were not diverted. Excavation was carried out during wet season
c) Smooth blasting and presplitting techniques	Conventional and some uncontrolled blasting.
d) Gunite to be applied to all slopes just after cutting. Additional reinforcement e.g. bolting and mesh, to be decided by the technical supervision	Some gunite was applied to limited areas and at the end of the excavation



$J_E, J_W, J_S$  and  $J_N$  : Slope faces of the cutting

- Poles of discontinuities
- $P_i$  Dip direction of discontinuities
- ▲  $w_i$  Wedge intersection
- ⊙ Circle of internal friction

Fig. 2. - Stereoplot (Schmidt) of potential unstable planes and wedges anticipated by the design




Fig. 3. - Stereoplot of planes and wedges which presented instability during the excavation. Note that only planes  $P_2$  and wedge  $w_1$  shown major failure problems (see legend from fig. 2)

The contractor decided to excavate the pit walls to 60 degrees in all slopes and under the conditions listed in Table 2 (right column). When it was reached 10 m depth (half of the excavation) wedge  $W_1$  failed on the West slope. Nevertheless the excavation continued under the same conditions and when it was 20 m deep (almost end of the excavation) plane  $P_2$  failed on the North slope. Both failures allowed us to check the stability conditions during construction and to compare it with those predicted during the stage of design.

Fig. 3 and Table 1 show stability analysis of the discontinuities existing during excavation. In all cases the factor of safety - could be higher than 1.2 under design conditions (Table 2). However, wedge  $W_1$  and Plane  $P_2$  failed.

Fig. 5 shows the rock slide of wedge  $W_1$ . This wedge failure gave place to approximately

$15 \text{ m}^3$  of rubble rock on the West face of the cut. Fig. 3 and 4, and Table 3 present a synthesis of the stability analysis. Water pressure distributions are indicated in Fig. 4 for  $(C' + \beta')$  condition. In this case an acceleration "a" due to blasting expansion wave was also considered.

From these results it seems that overloaded blasting has been the main factor contributing to failure of wedge  $W_1$ . If it is assumed an acceleration of 0.20 g as usual for this situation, just a lower value, e.g. 0.18 g but with water forces acting on the slope can lead to a factor of safety of 1.0. However without water pressures it should be required an acceleration higher than 0.20, to get a factor of safety of 1.0 (Table 3).

Fig. 6 shows the excavation after the failure of plane  $P_2$  located on the North slope -

- $J_w$  - Plane of the slope face
- $J_1$  and  $J_2$  - Planes of wedge discontinuities
- $J_T$  - Plane of the tension crack
- $P_1$  and  $P_2$  - Poles of  $J_1$  and  $J_2$
- $N_{1,2}$  - Resultant of normal components of weight to  $J_1$  and  $J_2$
- $R$  - Resultant of weight and hydraulic force on  $J_T$
- $RG$  - Horizontal component of blasting force
- $FS_1$  - Factor of safety only with  $\phi$
- $FS_2$  - F. of s. with  $\phi + C$
- $FS_3$  - F. of s. with  $\phi' + C'$

Fig. 4. - Graphical analysis of the stability of wedge  $w$ , acting internal friction, cohesion, water pressure and acceleration due to blasting






Fig. 5.- Wedge failure ( $w_1$ ) on the West face of the excavation



Fig. 6.- Plane failure (P2) on the North face of the excavation (see man in the circle for scale).

when it reached a depth of 20 m. The volume of fallen rocks was about 400 m<sup>3</sup>. Table 3 summarized the stability conditions of this plane and it is shown that for design purposes (Table 2) the factor of safety should be higher than 2.0. It was concluded that the main reasons of the failure was the presence of water in a tension crack. Other possible reasons could be the loads of the lorries along a road sited just on the top of the excavation (Fig. 6), and the loosening of the rock by conventional blasting patterns.

TABLE 3.- STABILITY CONDITIONS OF WEDGE W<sub>1</sub> AND PLANE P2

CONDITIONS	FACTOR OF SAFETY	
	WEDGE W <sub>1</sub>	PLANE P2
$\phi$	1,11	-
C + $\phi$	2,04	1,21
C + $\phi$ + tension crack on top	-	1,17
C' + $\phi'$	1,70	0,81
C + $\phi$ + a (a = 0.28 g)	1,0	-
C' + $\phi'$ + a (a = 0.18 g)	1,0	-

#### DISCUSSION AND CONCLUSIONS

The expansive nature of the material and clayey fillings along the discontinuities have largely controlled the behaviour of the Olazagutía marls. In spite of borehole drilling cores and excellent outcrops some of the discontinuities shown different orientations than those anticipated during site investigations. It was demonstrated that if design recommendations were maintained no major failures could be - occurred during construction. The main reasons of the failure of wedge w<sub>1</sub> was the conventional blasting without any pre-splitting or smooth firing and the overloaded charges used. It - was shown that if a geotechnical assistance - would be carried out during construction the blasting effects could be minimized by means of a drilling pattern, being able to accommodate blasthole downlines favoring northward plunging (Fig. 4). Water pressures along a tension crack on the top of the slope seems to be - the main reason of the failure of plane P2. Other causes could be the conventional

conventional blasting and the loads of the lorries passing along a road just on top of the slope.

In this case some questions has been raised up:

- The importance of controlling the seepage of rainfall water in the excavation area.
- The need to of undertaking smooth blasting - and to consider the effects of blasting in the stability analysis of rock slopes in order not only to optimize the design but to recommend the best blasting schemes, too.
- The need of geotechnical advice during construction as a part of the design in order to accommodate the conditions anticipates during design and those prevailing during construction.

#### ACKNOWLEDGEMENTS

The authors are grateful to Dr. A. Uriel from the Laboratorio del Transporte y Mecánica del Suelo (Spain) for his comments during the preparation of this paper, and to Dr. F. Ojeda, Head of the Geotechnical Dept. of The Empresa Nacional Adaro (Spain), for his help.

#### REFERENCES

- González de Vallejo, L. and Berzal, J. L. (1976).- Geotechnical properties of the Olazagutía Marls (in spanish). Nat. Symp. on Soft Rocks. Soc. Española de Mec. de Rocas Madrid, I, A-2.
- Hoek, E. and Bray, 1974. Rock Slope Engineering. Inst. Mining. and Met. London.
- John, K. W. 1971.- Three Dimensional Stability Analysis of Slopes in Jointed Rock. Int. Symp. Open Pit Mine Planning, Johannesburg.